



*Overall view of the revised Chancel and Sanctuary area.* The organ was moved further back left, while the altar was moved down and forward closer to the Nave. The old chancel and communion rails were removed; there are now new communion rails (no finish applied yet), with new padded kneelers. The pulpit was removed and the lectern was moved down into the Nave to be used as an ambo. The flowers were moved from the shelves on the wall with the large cross to in front of the altar and to a single plant stand. Lights were re-pointed at the large cross and replaced with spotlight bulbs to highlight and bring out the carved features of the cross. The Bishop's chair was moved to the left side near the altar. Last, the credence table was moved forward near the new location for the altar.



*Closeup of the moved altar and flowers in their new location.*



*Closeup of a new communion rail and kneeler in its new location.*



*The revised rear area of the Nave looking into the Narthex. Two old pews were removed from the back of the Nave, along with 10 chairs. The baptismal font and the paschal candle were moved to the rear of the Nave. Both side walls and the rear wall of the church were repaired and re-painted a light blue color. The doors entering the Nave are being left open for easier access.*



*Closeup of the large Sanctuary cross highlighted with spotlights.*



*Closeup of the plant stand and credence table in their new locations.*



*New glass door to worship space from the meeting hall installed; replaces old worn solid wood door.*